



ROADWAY & LANDSCAPE RESTORATION CURB AND SIDEWALK

REVISED 4/11/15
N.T.S.

NOTE:

1.) PAVEMENT REPAIR TO EXISTING PAVEMENT SHALL CONSIST OF 2" OF HMA 9.5M64 SURFACE COURSE AND 5" OF HMA 25M64 BASE COURSE MATERIAL.

2.) LANDSCAPE REPAIR SHALL CONSIST OF 4" OF SCREENED TOPSOIL AND SOD, UNLESS THE WIDTH OF THE RESOTRATION IS LESS THAN 6" WHICH CAN BE RESTORED WITH 4" OF SCREENED TOPSOIL, FERTILIZER, SEED AND HAY MULCH.